


- Thursday evening, **one of the interface board power supplies in the West cathedral area failed**
- **Opened West CF** (North and South EF irons open all week) Friday morning
  - ◆ Replaced power supply
  - ◆ This was the “untested spare” we had to install 7 weeks ago as a consequence of a water leak






- Attempt to **reproduce / understand toroid related noise** (Monday)
  - ◆ Tried to raise humidity
  - ◆ Run magnet up to 2500A (normal operating point is 1500A)
  - ◆ **No noise observed**
- **Prevent future occurrence of noise**
  - ◆ All magnet connection bolts were torqued to 55 foot pounds
    - Some were quite low – one required about 1.5 turns to get to 55 foot pounds
  - ◆ Measured west CF taps (10 coils) with  $\mu\Omega$  meter
    - Resistances ranged from 5 to 11  $\mu\Omega$
    - One was 27  $\mu\Omega$  (65 W at 1500A) – low torque, took  $\frac{3}{4}$  turn to get to 55 ft pounds
  - ◆ Installed voltage taps on the West side



- “Checkerboard problem” – resolved!
- Discrepancy between L1 and precision readout for high  $E_T$  EM objects in certain region of the calorimeter
- Can correct offline
- Discrepancies between reported gain and ADC counts
- Traced down to tight timing interval between arriving control signals
  - ◆ Relaxed timing in firmware



$\eta/\phi$  distribution of all candidate EM objects:

$p_T > 25 \text{ GeV}$   
 $\text{EM fraction} > 0.9$   
 $\text{isolation} < 0.15$   
 $\text{HMx8} < 20$



# Shutdown Completion

- **Detector closed** (remove scaffolding, close EF's + West CF) this morning
- **Secured collision hall** by 14:30
- **Running magnet** for ~24 hours from Monday afternoon
- Plan to **take cosmics** with the complete detector tonight / tomorrow
  - ◆ We need access time Tuesday afternoon or Wednesday to complete outstanding work in the collision hall