

# Quality Assurance for L0

**Purpose:** monitor sensors from HPK  
make sure we can build L0 detector

**Documentation:**

Run IIb Quality Assurance Document  
D0note 4120, draft 4.0

**Testing sites:** HPK, Fermilab, Stony Brook

**Irradiation:** Kansas State University

# Overview

The sensors received from HPK for RunIIb were excellent.

Based on that experience, only a small fraction of the sensors will be selected for detailed mechanical and electrical tests by us. This fraction (currently 10%) could change depending upon what we find.

# Tasks at Fermilab

- initial registration upon receipt from HPK
- visual inspection of each sensor
- mechanical measurements (on 10%)
- electrical measurements on each sensor
  - I-V and C-V measurements
- stability - I(time)
- special measurements as appropriate
  - on sensors, diodes, and test structures

# Visual Inspection

Verify defects found at HPK

Check using a probe station with video camera for selected sensors (about 10%, or if flagged by HPK):

- edge chipping ( $< 50 \mu m$ )

- processing abnormality

- breaks in bias resistors

- alignment of metallization with implant  
( $> 2$ microns on each side)

# Mechanical Measurements

Using an optical metrology system:

wafer thickness  $320 \pm 20 \mu m$

wafer warp, best effort  $< \pm 50 \mu m$

cutting lines

accuracy  $\pm 10 \mu m$

parallelism  $\pm 5 \mu m$

# Whole Detector Measurements

## Measurement

## Bad Detector

### C-V

measure capacitance versus voltage  
determine Full Depletion Voltage

FDV > 300 V

FDV < 40 V

### I-V

measure current up to 800 V

$I_{tot} > 1 \mu\text{A}$  at 700V

Number of bad strips

>1%

# Strip Measurements at SB

(during a scan under computer control)

## Measurement

## Bad Strip

<b>Idiel</b>		>10 nA (PINHOLE)
	current through the coupling capacitance	
<b>Cac</b>	(at 100 Hz)	> 1.2*mean (OPEN)
	coupling capacitance	< 0.8*mean (SHORT)
<b>Istrip</b>		> 10 nA (LEAKY)
	leakage current to a strip	
<b>Rpoly</b>		> 1.1 MOhm or < 0.5 MOhm
	polysilicon resistance	
<b>Rint</b>	(even pairs only)	< 2 GOhm
	interstrip resistance	
<b>Cint</b>	(even pairs only)	> 8.4 pF (0A)
	interstrip capacitance (at 100kHz)	> 14.4 pF (0B)

# Testing Sites

Test	HPK	Fermi	SB
inspection		10%	
mechanical		10%	
I-V	100%	100%	10%
C-V	100%	100%	10%
Idiel	100%		10%
Cac	100%		10%
Istrip	TS	TS	10%, TS
Rpoly	TS	TS	10%, TS
Rint	TS	TS	10%, TS
Cint	TS	TS	10%, TS

TS=Test Structures


## Additional TS Measurements as needed at Fermilab and Stony Brook


- total strip capacitance
- metal series resistance
- implant resistance
- flat band voltage
- coupling capacitor
- coupling capacitor breakdown voltage

## Equipment at Stony Brook


probe station	Alessi 6100
strip probes	4
bias line probe (rides chuck)	1
Source Measure Unit (voltage source with picoammeter)	Keithley 237
voltage source	Keithley 487
picoammeter	Keithley 487
LCR meter	Agilent4263B
4 X 8 Matrix Switch	HP34904A

We use the matrix to perform multiple tests while only touching each pad once. We touch AC and DC pads of neighboring strips and complete the scan in pairs. One probe always even, one always odd. This enables interstrip measurements at the same time.





## Stony Brook Plan for use of the Matrix




# Measurement Techniques

bias voltage	All measurements at FDV+20V.
Idiel	put 80V on AC pad and measure current out of SMU to bias line at ground.
Cac	measure capacitance between the AC pad and the bias line at $f=100\text{Hz}$
Istrip	measure current to the DC pad at ground with the K487
Rpoly	apply a voltage to the DC pad with the SMU and measure current from the SMU to the bias line at ground
Cint	measure capacitance between the two AC pads
Condint	Apply a voltage with the SMU to one DC pad and measure current to a neighbor at ground with the K487


# Measurement Procedures

- Repeat obviously bad measurements:
  - The bias line loses contact: Strip currents approach the total leakage current.
  - SMU mode problem:  $R_{poly}$  is infinite and  $I_{diel}$  is very small for all strips.
  - [Neither of these has caused a problem recently.]
- Remeasure bad strips, to see if the problem is a result of bad contact.
  - If the bad measurement value repeats once, the strip is called bad.**
- At the end of the scan lift both probes to measure the background and do a two-strip scan. The background values of  $I_{diel}$ ,  $C_{ac}$ ,  $I_{strip}$ ,  $C_{int}$ , and  $C_{dint}$  are then subtracted from corresponding values for all strips. (We should subtract conductances in measuring  $R_{poly}$ , but do not bother since the correction is very small.) The background values are generally a small fraction of the bad strip limit.


# IV




# CV




# Idiel




### Cac




# Is trip




# Rpoly



# Cint



# Condint



# Advantage of the matrix

make all the measurements at the same time

good diagnostics - problems are due to bad contact

contact

most sensitive measurement

bias line

Condint

AC pad

Cac

DC pad

Rpoly

# History

We have done cross-calibration studies between HPK, Fermilab, KSU, and SB.

We know how to measure FDV, total currents, and strip properties.

At SB we have tested 24 L2 sensors.

The first 15 were perfect. Rate of bad strips less than  $10^{-4}$ ! Then selected problems and found 10 bad strips in remaining 9 sensors.

**No sensor had  $>1\%$  bad strips.**

# Irradiation

KSU will irradiate a few sensors and test structures to about  $10^{13}$  neutrons/cm<sup>2</sup> (1 MeV equivalent)

These sensors and test structures will be tested at Stony Brook before and after irradiation.