

Summary of Installation Activities: 4/7/2006

L1 Calorimeter Trigger Upgrade

1. I finished cabling M105.
2. Dan informed me that pulsing M103 earlier this week indicated that two channels were shorted (cables need repair), and three channels had BLS preamp or hybrid problems.
3. I pulsed M105 (skipped M104, which I will pulse tomorrow). Two channels are shorted (need cable repair), and one channel has BLS preamp or hybrid problem.
4. So, shorted cable count is 8 out of 3x128 channels.
5. I am keeping all this information on channels in a homemade database.
6. Mike continued to work on TAB/GAB links and related issues.

Please see the web for details. URL is <http://d0server1.fnal.gov/users/selcuk/www/default.htm>. This information is on the trigger online logbook also.

Selcuk Cihangir