

## **Summary of Installation Activities: 4/11/2006**

### **L1 Calorimeter Trigger Upgrade**

1. I finished cabling M107. That is the 7<sup>th</sup> rack cabled out of 10.
2. Norm fixed the pulser PS, then I pulsed the fourth patch panel cables on M106 and all of M107. Three more channels on M106 are shorted. On M107, three cables are shorted, one seems shorted, but I believe, the pins on the front of the patch panel are faulty. I will confirm that later.
3. So, shorted cable count is 14 out of 6x128 channels.
4. Mike and Ted continued to work on TAB/GAB – L2/L3 links and related issues while Sabine worked on algorithms and firmware.

Please see the web for details. URL is <http://d0server1.fnal.gov/users/selcuk/www/default.htm>. This information is on the trigger online logbook also.

Selcuk Cihangir