

## **Summary of Installation Activities: 4/19/2006**

### **L1 Calorimeter Trigger Upgrade**

1. I worked again to determine if the problematic cables are shorted so that we can fix them. Dean helped. We used a cable tester, a TDR (Time Domain Reflectometer, I think it is called). It was not much help. I asked Dan's suggestions. I will get back to it again tomorrow.
2. One box of the new LVDS cables, 80 of them, have arrived. Mike and Ted are testing one of them now while I am working on the labels.
3. Mike suggested a new label format for the LVDS cables. I am making the input files. We will print them tomorrow. I believe we have some blank labels.

Please see the web for details. URL is <http://d0server1.fnal.gov/users/selcuk/www/default.htm>. This information is on the trigger online logbook also.

Selcuk Cihangir