

Notes:
J1 is the first HDI Hirose connector.
J2 is the second HDI Hirose connector.
J3 is the 50 pin 3M connector for grey 0.25inch P.F.R.C.
J4 and J5 are 20 pin 3M connectors – carry additional HDI signals.
J6 and J7 are 20 pin 3M connectors – provide external power.



ITEM	PART NUMBER	DESCRIPTION OR SIZE	QTY
PARTS LIST			

UNLESS OTHERWISE SPEC.	ORIGINATOR	Matulik/Utes	08/13/98
FRACTIONS / DECIMALS / ANGLES	DRAWN	M. Matulik	06/13/98
	CHECKED		
Fri May 07 1999 09:35:24	APPROVED		
	USED ON		
	MATERIAL		

FERMI NATIONAL ACCELERATOR LABORATORY
UNITED STATES DEPT. OF ENERGY

Interface Module Prototype

SCALE	FILMED	DRAWING NUMBER	Sheet 1 of 5	REV.
		3823.112–EB–330109		F