

# Issues

- \* On store 3506 we had a fiber tracker read-out rack tripping twice on water flow. Troubles recovering.
- Short accesses to the Collision Hall for Forward Muon and Calorimeter.
- Over the week-end a fan failed (between stores) in a muon trigger rack (repaired in an access).
- Collision Hall Ambient He level are high. Usually  $\sim 100$ ppm, now up to 400ppm. Of concern for PM in the Hall