



Status report 12/20/04

M.Weber, FNAL




The emphasis was on detector checkout and not yet on running at high efficiency.

Beam avg y position per run



Beam position is now OK
Stability is now the priority
(has been OK sofar)

Lost cooling water from C4 pump house




- Had to power down the experiment Mon eve
- We were up again for store 3845 Tue morning (but without 1/6 of the silicon, due to a failed PS)

Access to the cathedral

- To repair the silicon PS we had to open the detector on Wednesday
- Open, replace PS, close
- Took the opportunity to recover individual muon channels

L3 problem above 50E30

Not able to efficiently run with the newest trigger-list



- investigating...