



Putting ferrite onto power lines




- 4 modules in the same phi sector
- The other power lines unplugged
- 100 ohm isolation




Different ferrites


core (5 turns)




ferrite (5 turns)




another ferrite (5 turns)



another ferrite (10 turns)



Something out of control...



- The same setup with the last plot in previous page, but the noise is much small...